

ICDs (InterConnect Defects)

What are they?

Where do they come from?


**How can we make them go
away?**

Doug Trobough
Suixin Zhang

Definition of ICD

- **ICDs are any defect that occurs adjacent to the innerlayer copper post**
- **Some common types are smeared resin, hole debris, and post separation**
- **ICDs are broken up into 3 categories**
 - Type I – Between inner layer copper and electroless copper
 - Type II – Between electroless copper and electrolytic copper
 - Type III – Elsewhere in copper
- **We will only refer to Type I**

Example of ICD types



Categorizing Type 1 ICDs



■ Debris type

- (Debris interfering with interconnect bond)
 - Drill debris
 - Smear
 - Dielectric filler powder

■ Separation type

- (Separation of interconnect bond)
 - Copper cleanliness
 - Drill work hardening
 - Rinsing residue
 - Poor electroless copper quality

- **This approach helps communicate root cause**



Why do we care?

- **Type 1 Debris type ICDs are not closely related to finished product defects**
 - Fail IPC and Military specifications – Product generally can't be shipped
 - Have been tested at multiple companies without exhibiting significant impact on through hole reliability
- **Type 1 Separation type ICDs are closely related to the formation of open circuits in assembled PCB's.**
 - Valid reliability concern
 - Specification failure

ICD debugging comments

- **In general, not enough work is done to determine what type of ICD is occurring**
- **Dominant response to ICD is to increase desmear level**
 - Works on smear and debris
 - But is not necessarily the root cause
 - Can make Separation type ICDs worse
- **Desmear process changes by PCB fabricators are common, but very hesitant to change electroless copper parameters**

Debris Type

Where do they come from?

■ **Direct Cause**

- Debris generated during the hole drilling process coats (or sticks to) the drilled hole wall
 - Debris is not entirely removed during post drill cleaning – Primary cleaning is called desmear process (or smear/debris removal processing)
 - Debris interferes with formation of “flawless” interconnect interface
- **Debris type ICDs are visible as built, and do not require thermal stress to occur.**

Primary Debris Type ICD causes

■ Drilling



- Hot drill bits do not drill cleanly and create more debris, that tends to be adherent to the copper and hole walls
- Worn drill bits tend to heat up easier and have the same appearance as Hot drill bits.
- Sub-optimal drill parameters or drill bit design

■ Desmearing

- Many low Dk, low Df materials are more chemically resistant than standard epoxy (FR-4) type materials
 - More aggressive desmearing is required
 - Plasma etching processing is effective on these material
 - Enhanced chemical desmear processing may be needed
 - Enhanced process control tools may be required



Contamination Type Debris

- This type has gotten the most attention in Asia
- Main cause
 - Powdery debris after drilling



Examples of Debris Type

- **Note lack of wicking and glass protrusion**
 - Bad plasma or poor chemical desmear



Separation Type ICDs

Where do they come from?

- **The primary characteristic of this failure type, is that a copper to copper bond is pulled apart during thermal exposure**
 - Normally visible only after thermal stress or reflow
- **Two modes**
 - Low strength – Copper plating bond is too weak to handle normal stress levels during thermal exposure
 - High stress – Design and material related. Additional stress is concentrated on specific interconnect locations

Primary Separation Type ICD causes


■ **Low bond strength**

- Poor plating adhesion to the hole wall
- Lack of good bonding surface in hole wall
- Lack of clean oxide free copper surface in the hole wall
- Electroless copper properties are poor


■ **High Stress during thermal exposure**

- High CTE material
- Design resin content
- Very thick copper plating
- Nickel plating
- Larger hole size
- Board thickness
- Interconnect pad configuration


Examples of Separation Type ICDs



Examples of Separation Type ICDs Continued



Post Separation Type



D-Void Type

Getting Rid of ICDs

- **ICD formation is strongly related to two key factors**
 - PCB fabricator processes
 - Raw material type
- **Capable and consistent processes in drilling is best approach**
 - Avoids creation of ICDs
- **If ICDs are found follow this path**
 - Review samples and findings from problem orders
 - Identify the type of ICD
 - Follow troubleshooting method for this type of ICD

Debris ICD Type Troubleshooting Drilling

- **Drilling generates the debris that causes most of this type of ICD.**
- **Get drill parameters under control**
 - Good vacuum levels at drilling
 - Correct chip load
 - Correct cutting speed
 - Bits in good shape, not worn or damaged
- **Beware of combinations of high cutting speed and low chip loads**
 - This combination creates high heat levels and more debris
- **Significant copper nailheading is commonly found with Debris based ICDs**
 - Reducing nailheading helps reduce debris ICDs
- **Assess drilling quality using SEM of half holes**

Debris ICD Type Troubleshooting Desmear

- **Desmear removes the debris generated by drilling – Good desmear is critical for consistent results**
- **If using Plasma Etching, Get weight loss under control – Efficient etching**
 - Temperature control is the main issue
 - Etch rate rises with time if panels are cool at the start
 - Hot panels may have overetch and plating adhesion issues
 - Dry boards before plasma etching – water vapor from dielectric reduces plasma etch effectiveness
 - Measure etch rate on coupon with drilled holes, not surface coupons
 - Weight loss of 30mg/DM2 in holes, or 45-50mg/DM2 for surface coupons is a good target
- **PCB Fab's with good Plasma Etching process have very little ICD issues, when plasma etching is used – Best Practices**
 - Dry and preheat panels, load panels “warm-hot”
 - Control weight loss amount and even distribution of weight loss over full load
- **SEM's of half holes is the best tool to characterize Plasma Etching process effectiveness, along with weight loss control.**

Debris Debugging Chemical Desmear

- **Chemical desmear has two functions**
 - Effective at washing out debris
 - Removes resin – Removal rate is very dependent on dielectric resin type
- **Chemical desmear issues**
 - Sweller type
 - Some materials not compatible with all sweller types – particularly NMP type
 - Weight loss
 - Similar to plasma etching, characterize and keep this process under control
 - Chemistry control
 - High MnO₂ levels can cause debris to form
 - Agitation, rinsing, ultrasonics
 - Very important on chemical desmear lines
 - Permanganate bathes are very viscous so agitation is critical
 - Good performing PCB fabricators have very good agitation

Separation ICDs

Strength of Interconnect

- **Creating a strong connection between the innerlayer copper and the electroless copper layer is the best way to avoid ICDs**
- **The following is a partial list of factors affecting interconnect strength**
 - **Good metallurgical copper bond**
 - Clean copper, no chemical residues
 - Oxide free copper surface
 - Good grain structure on copper foil
 - **Strong electroless copper**
 - Appropriate thickness
 - Controlled deposition rate (not too fast)
 - Good grain structure
 - **Good hole wall adhesion**
 - **Copper foil thickness**
 - Thicker is better
 - **No localized drill damage**

Separation Type ICD Debugging

Strength of bond

- **Determine copper etch weight loss**
 - Best over 30u" (0.75 um) removed in holes
- **Use good water quality on electroless copper line rinsing**
 - Over desmear can also lead to rinsing issues
- **Improve hole wall adhesion**
 - Good desmear, with adequate texture
 - Don't over desmear or use too high temperature desmear

Separation Type ICD

Stress Causes

- **High z-axis expansion**
 - High resin content
 - Low TMA Tg
 - High expansion material
- **Poor copper hole wall adhesion**
 - Puts strain on interconnects, instead of distributing through out hole wall
- **Design factors**
 - Tight grid hole patterns
 - Large hole size
 - Pads only on layers 2 or N-1
 - Board thickness
 - Localized resin content (regions requiring high resin fill)
- **Solder shrinkage in holes**
 - Pulls copper away from hole wall
- **Uncontrolled or over-temperature exposure**
 - Poorly controlled solder fountain rework (example)
- **Constraining surface finishes**
 - ENIG, Electrolytic Nickel/Gold

Separation Type ICD Debugging Stress Reduction

- **Process to achieve good hole wall adhesion**
 - Allow options for single ply and heavier glass styles
- **Reduce resin content in the stack-up**
- **Do not use nickel plating**
- **Avoid design factors**
 - As noted on previous slide

General Commentary

- **ICDs are rare in the US and Europe**
 - Long history of Military and High Reliability electronics has resulted in good processing practices
- **ICDs are PCB process related**
 - Strong processes with good process control do not see significant problems
- **Some material types are more likely to have ICDs**
 - Materials with inorganic fillers, and more chemically resistant resin systems
 - Require tighter processing windows, or extra desmear steps, to achieve excellent results
 - Plasma etching is more common on these types

Summary

- **ICDs are a significant PCB industry issue, primarily in Asia.**
- **High performance material systems are more likely to have ICDs**
- **Many fabricators have consistently good results, no ICDs**
 - Use best practices at drilling and desmear
- **ICD type identification, good engineering, and good controls have been effective at eliminating ICDs**
- **Isola and other companies continue to perform Research into the causes of ICDs**
 - Working to make the system more robust